

The Columbia Accident: Synopsis of CAIB Report* Regarding the Physical Cause of the Accident and and Personal Thoughts


James O. Arnold, Ph.D

**University of California at Santa Cruz
NASA Ames IPA
Investigator, CAIB, Engineering Group 3**

***Seminar based on CAIB Appendix F2, Vol IV
by J. O. Arnold, H. E. Goldstein and D. J. Rigali**

September 27, 2011

The Board



Board Members

Back Row (from Left)

Dr. Douglas D. Osheroff, Professor of Physics and Applied Physics, Stanford University

Maj. General John Barry, Director, Plans and Programs, Headquarters Air Force Materiel Command

Rear Admiral Stephen Turcotte, Commander, Naval Safety Center

Brig. General Duane Deal, Commander, 21st Space Wing, USAF

Maj. General Kenneth W. Hess, Commander, Air Force Safety Center

Mr. Roger E. Tetrault, Retired Chairman, McDermott International, Inc.

Front Row (from Left)

Mr. Scott Hubbard, Director, NASA Ames Research Center

Dr. James N. Hallock, Chief, Aviation Safety Division, Department of Transportation, Volpe Center


Dr. Sally Ride, Professor of Space Science, University of California at San Diego

Admiral Harold Gehman, Admiral, US Navy (retired) - Chairman


Mr. Steven B. Wallace, Director of Accident Investigation, Federal Aviation Administration


Dr. John Logsdon, Director of the Space Policy Institute, George Washington University

Dr. Sheila Widnall, Professor of Aeronautics and Astronautics and Engineering Systems, MIT




Physical Cause





Assignment: “Follow the TPS”


- Confirm or Refute: “During the launch of STS 107, a briefcase-sized piece of foam from the External Tank struck the Reinforced Carbon-Carbon (RCC) Left Wing Leading edge of Shuttle Columbia compromising the RCC. During entry, the damage to the RCC led to the structural failure of the wing, the tragic loss of Columbia and the STS 107 crew”
- This was the first, obvious loss of any U.S. vehicle during hypervelocity atmospheric entry, greatly complicating the investigation.
- CAIB board member, G. Scott Hubbard assigned the “Follow the TPS” task to J. O. Arnold, H.E. Goldstein and D. J. Rigali on February 6, 2003, less than a week after the accident. The results were published in August, 2003.




What did we know early in the investigation?



- Combined background in aerothermodynamics, Shuttle tiles and carbon-carbon
- Knowledge that superheated shock layer gases had entered the left wing box, very probably melting the aluminum substructure, and in essence, sawing the left wing off from the inside-out.
- Very poor quality imagery of the foam strike - no underside view
- Amateur video of entry from California coastline to Texas, including the Starfire photograph taken in New Mexico
- NASA data tracking, but No Orbiter Experiments (OEX) on-board engineering data - this was stored on board on magnetic tape and subsequently was recovered.

Frame 4912






Bi-Pod Ramps




Starfire Photo from Kirtland AFB GMT13:57:14




Starfire Optical Range Image (26 March 2003)
model overlay (R. Cleis, R. Fugate, R. Johnson)
image sharpened using deconvolution (J. Christou)

The model scaling and orientation are based on telemetry (latitude, longitude, and altitude from NASA) and observations (azimuth, elevation, and range from SOR). The image scaling and orientation were derived from measurements using star fields. The Columbia model was provided by NASA.




Background: Shuttle Aerothermodynamics & TPS

- Entry Trajectory
 - Normalized aerothermodynamic entry heating profile
 - Zoom-in on wing leading edge
 - Space Shuttle Thermal Protection System
 - Huge, national efforts in CFD, Thermal Analysis, Aero, etc started soon after the accident, led by NASA JSC



Entry trajectory

Figure 1 (a) Normal entry; Geodetic Altitude Vs
GMT Entry Interface EI
at 400,000 ft/ Mach 24. Angle of attack 40 degrees



Entry heating









Figure 1 (b) Normal entry; Normalized Heating Rates Vs
GMT Entry Interface EI
at 400,000 ft/ Mach 24. Angle of attack 40 degrees



Space Shuttle - Bow shock layer and surface temperatures*




Gas Temperatures from CFD Solution
Pitch plane, Near Peak Heating.
Angle of attack: 40 degrees,
246,000 ft altitude, Mach 22.91 at 13:50:53





Surface Temperatures from CFD Solution
Near Peak Heating.
Angle of attack: 40 degrees,
246,000 ft altitude, Mach 22.91 at 13:50:53

*CFD By NASA Ames, J. Brown, R. McDaniel and D. Prabhu





CFD Solutions for wing leading edge



Surface Temperature









Surface Pressure




Overview of Space Shuttle TPS



 RCC
 HRSI Tile
 LRSI Tile
 AFRSI
 FRSI



**Thermal maps
from flight data**





RCC leading edge system



HRSI tile system


- LI-900
 - LI-2200
 - FRCI-12
- Multi-use
Temperature < 2300 F






Orbiter Experiments (OEX) sensors and data



- Key Sensors and their locations on the orbiter. Shuttle Columbia was the only vehicle fitted with OEX sensors.
- Out-family sensor readings for STS 107. Tape recorder was recovered from the debris field. By a miracle, the tape was OK.
- Time-line of sensor readings and interpretation



OEX Sensors, inside wing, behind spar




OEX sensor locations






OEX STS-107 Flight Data







OEX STS-107 Flight Data and Thermal Analysis by JSC/C. Madden





“Typical” Off Nominal OMS Pod Temps.






LaRC Wind Tunnel Tests Data help explain cooling trends on OMS pod


Effect of Missing RCC Panel on Orbiter Leeside Flowfield as Inferred From Surface Heating Patterns

Mach 6 Air $\gamma_{\text{eff}} = 1.4$ $\alpha = 40$ deg $Re_{\infty, L} = 2.4 \times 10^6$ $\beta = 0$ deg


Conceptual sketch of Orbiter leeside flowfield




Wing leading edge damage influences leeside flowfield



Baseline





Missing panel #5




Missing panel #10

Note cooling trend on left OMS pod






More OEX data and interpretation




OEX/MADS STS-107 Flight Data



Mar 29, 2003 06:55

V07T9666A-STIS-050	—	V07T9666A-STIS-090	---	V07T9666A-STIS-107	----
V07T9666A-STIS-073	---	V07T9666A-STIS-093	----	V07T9666A-STIS-109	-----
V07T9666A-STIS-087	-----	V07T9666A-STIS-094	-----		



NASA Langley/(Gnoffo) Orbiter Surface Streamlines EI+404; Mach=24.9; Alt.=243k ft


Attachment Line


- Line that separates flow that stays on windward side to flow that wraps around to leeward side.

Outline of RCC Leading Edge Panels


Outline of Main Landing Gear Door

~ Location of V07T9666A







OEX/MADS STS-107 Flight Data



Mar 29, 2003 06:57


V09T9895A-ST5-050	—	V09T9895A-ST5-090	---	V09T9895A-ST5-107	----
V09T9895A-ST5-073	- - - -	V09T9895A-ST5-093	- . - .	V09T9895A-ST5-109	- - - -
V09T9895A-ST5-087	----	V09T9895A-ST5-094	----		






Analysis of the Columbia Debris

- Huge effort start & ongoing to recover debris from the field
- Huge effort at KSC to identify parts
- CAIB, NASA and Contractor teams conducting forensics at KSC



FRCC Panels 8/90 Ribs (Inboard View)






Reconstructed RCC Panel 8/9 Area





Probable Initial Breach in Panel 8






Close up of lower edge of panel 8/9

Outside of thermal
barrier slot


LI 2200 Carrier
Panel Tile






Foam Impact Testing

- CAIB lead: G. Scott Hubbard. Paul Wilde (CAIB) was lead on “Follow the Foam”. Large modeling effort led by JSC NASA and included work by Sandia
- Tests on tiles conducted first, little damage
- Then tests on fiberglass simulating RCC
- Tests on actual, aged RCC in one-for-one ground test
- Conclusive evidence that foam impact was initiating event




Wing Leading Edge Test Set Up






Mon Jul 07 2003 13:29:08.509059 S



Physical Cause

- Loss of Columbia and its crew was caused by breach in the Thermal Protection System on the leading edge of the left wing.
- The breach was initiated by a piece of insulating foam that separated from the left bipod ramp of the External Tank and struck the wing in the vicinity of the lower half of Reinforced Carbon-Carbon panel 8 at 81.9 seconds after launch.
- During re-entry, this breach in the Thermal Protection System allowed superheated air to penetrate the leading-edge insulation and progressively melt the aluminum structure of the left wing
- Weakening of the structure increased until aerodynamic forces caused loss of control, failure of the wing, and breakup of the Orbiter.



Acknowledgements Regarding “Follow the TPS”

- Howard Goldstein - Retired NASA
- Don Rigali- Retired Sandia
- NASA & NASA Contractor Engineering Staff
- Larry Korb
- Mike Ehret
- Don Hendrix
- Lisa Chu-Theilbar
- James Reuther
- Greg Kovacs
- Mark Tanner
- Jay Grinstead

References:

- Follow the TPS (Arnold, Goldstein and Rigali)
CAIB Report, Vol IV, Appendix F2, August, 2003
- Aero/Aerothermal/Thermal/Structures Team Final Report
CAIB Report, Vol V, Appendix G13, August, 2003



“This cause of exploration and discovery is not an option we chose; it is a desire written in the human heart... We find the best among us, send them forth into unmapped darkness, and pray they will return. They go in peace for all mankind, and all mankind is in their debt.”

President George W. Bush, February 4, 2003